

16" BOOT HYDRAULIC HOOKUP – INSTRUCTIONAL BULLETIN

DATE	June 9, 2023
BRAND	AGI, Westfield, Hutchinson, Mayrath, GrainMaxx
PRODUCT	X ² , MKX ² , HX ² , GM ²
MODEL	16-85, 16-105, 16-125
DETAILS	Instructions on how to connect the hydraulic hoses at the boot manifold properly.

We are getting reports that some assemblers are incorrectly connecting the hydraulics at the boot manifold. This affects the functionality of the auger and can easily be corrected. In some instances, there have been reports that the axles only steer one way. This happens because the steering hydraulics are hooked up to the cylinder block (smaller one) when they should be in the steering block (bigger one). Please refer to the image below for proper plumbing:

There is also a YouTube video available for further clarification:

<https://youtu.be/jHleaeKHes4>

